

## COLORS AVAILABLE

&gt; Refer to Stock Service Color Card

## INDUSTRIAL FINISHING

- We recommend washing at 35° in gentle cycle during 3 minutes using a softener that does not exceed 4% of the weight of the material considering the finishing expected. Centrifuge for 2 minutes. Dry. Use manual iron. If the fabric turns out excessively felted, the washing time or temperature should be reduced.

## CARE INSTRUCTION



Hand Wash



Any solvent  
except  
tetrachloroethylene



Iron low



Do not bleach



Dry Flat

## COLOR FASTNESS (AVERAGE VALUES)

|        | Dry rubbing | Wet rubbing | Wash fastness |
|--------|-------------|-------------|---------------|
| Light  | 4           | 3           | 4             |
| Medium | 4           | 3           | 3/4           |
| Dark   | 3           | 2/3         | 3             |

TECHNICAL  
INFORMATION

|               |      |
|---------------|------|
| Dyeing method | tops |
| Knot type     | knot |
| Pilling       | 3    |

KETTLE SIZE  
(Kg.)

|     |
|-----|
| 50  |
| 95  |
| 190 |

SUGGESTED  
GAUGE

3gg

## NOTES:

Might occur bleeding in designs with white stripes and intense colors.

Consult our sales team about dyeing process that decrease bleeding risk on intense colors.

For minimum production quantities and customers' own colors please contact our sales representative or write us to [essentials@incatops.com](mailto:essentials@incatops.com).

Minimum for dark colors subject to revision.

For solid dark shades, the fastness value could be lower than the one mentioned above. For more information contact your sales executive.