INDUSTRIAL FINISHING - We recommend washing at 35° in gentle cycle during 3 minutes using a softener that does not exceed 4% of the weight of the material considering the finishing expected. Centrifuge for 2 minutes. Dry. Use manual iron. If a more pronounced plie is required, washing time or washing cycle revolutions should be increased, but the bath temperature must be reduced to avoid the felting effect.

CARE INSTRUCTION

TRILOGY NM 1/8

> Refer to Stock Service Color Card

ESSENTIALS

Hand Wash

except tetrachloroethulene

COLOR FASTNESS (AVERAGE VALUES) Wet rubbing

Wash fastness

7gg

Light	4	3	4	
Mediu	m <u>3/4</u>	3	3/4	
Dark	3	2/3	3	
TECHNICAL		KETTLE SIZE		SUGGESTED
INFORMATION		(Ka.)		GAUGE

Dru rubbing

NOTES:	

Might occur bleeding in designs with white stripes and intense colors.

hanks

knot

35

Fall Winter 26/27

COLORS AVAILABLE

Dueing method

Knot type

Pillina

Consult our sales team about dueing process that decrease bleeding risk on intense colors.

For minimum production quantities and customers' own colors please contact our sales representative or write us to essentials@incatops.com. Minimum for dark colors subject to revision. For solid dark shades, the fastness value could be lower than the one mentioned above. For more information contact your sales executive.

30

60

85

180